



Heber Public Utility District

1078 Dogwood Rd., Suite 103 • P. O. Box H
Heber, CA 92249
TEL. (760) 482-2440 • FAX (760) 353-9951
www.heber.ca.gov

December 10, 2018

Attention: Laura Fischer
General Manager

SUBJECT: Heber W.W.T.P. Operations from October 22, 2018 to November 22, 2018

- A. Major violations: (NONE)
- B. Minor violations (NONE)
- C. Major sewer spills (NONE)
- D. Main sewer Plugs: (NONE)
- E. UV System: Operating fine. Self- Cleaning. No Maintenance.
- F. Vactor Truck:

November 7, 2018: Clean and empty Tank #1 at Water Plant.

November 15, 2018: Expose broken sprinkler line at Tito Huerta Park.

November 15, 2018: Repair service line break at 40 W. Second St.

G. TOTAL OF MILES OF SEWER LINES CLEANED OR VIDEOED: 0.00 Miles.

H. From October 22, 2018 through November 22, 2018:
Heber Wastewater Plant received and treated 15.30 MG.

I. HPUD did not exceed the daily maximum flow (1.2 MGD) as of November 22, 2018.

Sincerely,

A handwritten signature in blue ink that reads "Lucas G. Agatep".

Lucas G. Agatep
Lead Wastewater Plant Operator



Heber Public Utility District

1078 Dogwood Rd. Suite 103 • PO Box H

Heber CA 92249

Tel:(760)482-2440 • Fax (760)353-9951

www.heber.ca.gov

December 5, 2018

Attention: Mrs. Fischer

Subject: November 2018 Monthly Report

On the billing cycles ending on the 22rd of November 24,549,000 gallons of water were used by our consumers, an average of 792,000 gallons was used per day.

On November 6, 2018, collected the monthly Trihalomethanes (TTHM's) samples and were sent to Clinical Lab of San Bernardino for analysis. The results came in on November 26, 2018 and were once again below the maximum contaminant levels (MCL) for TTHM's. The running annual average (RAA) MCL for TTHM's is 80 parts per billion (ppb) and we attained 55 ppb for the Mc Cabe site and 53 ppb for the Little Field site. Heber Public Utility District continues to be in compliance with the State and Federal Water Regulations.

On November 16, 2018 the .75 million gallon (mg) tank was placed back in service after the minor corrosion were repaired by Pacific Hydrotech sub contractor. The .75 mg tank was disinfected and bacteriological testing was conducted prior to placing the tank back in service.

On November 27, 2018 started to drain the 1.7mg tank. This tank also had minor corrosion and will undergo the same procedure as the .75mg tank.

If you have any questions, please contact me at (760) 427-4685

Sincerely,

A handwritten signature in blue ink, appearing to read "Francisco Rodriguez".

Francisco Rodriguez

Chief Operator

Heber Public Utility District



Heber Public Utility District

1078 Dogwood Rd. Suite 103 • PO Box H

Heber CA 92249

Tel:(760)482-2440 • Fax (760)353-9951

www.heber.ca.gov

December 5, 2018

Attention: Mrs. Fischer
General Manager

Subject: Water Distribution Report November 2018

- A) Water breaks (1)
 - 1. Intersection of Hawk and Palm Street

- B) Service Leak (1)
 - 1. 150 Main Street

- C) Work orders (48)

LEAK - METER LEAK-----	8
DIS - DISCONNECT-----	5
CON - CONNECT-----	6
INFO - TEST METER -----	7
MC - METER CHANGE-----	15
OCC - OCCUPANT CHANGE-----	4
WATER BREAKS-----	0
MISC-MISC REPORT-----	0
HYDRT-HYDRANT LEAK-----	0
TEMP-TEMP SHUT OF REPAIR-----	0
SWR-SEWER PLUG UP-----	1
FIREFLY-FIREFLY REPLACE-----	0
ODOR - ODOR(TASTE/SMELL)-----	0
TEST WATER PRESSURE-----	1
TOTAL ALL CODES	48

Sincerely,

A handwritten signature in blue ink, appearing to read "Francisco Rodriguez".

Francisco Rodriguez
Chief Operator
Heber Public Utility District