



Heber Public Utility District

1078 Dogwood Rd. Suite 103 • PO Box H

Heber CA 92249

Tel:(760)482-2440 • Fax (760)353-9951

Nov 08, 2018

Attention: Mrs. Fischer
General Manager

Subject: Water Distribution Report October 2018

A) Water breaks (1)

1. 4 Main Street

B) Service Leak (1)

1. 59 Mc Cabe Road

C) Hydrant Relocation (1)

1. Corner of South West Corner of Hwy 86/Heffernan St.
(Hydrant was relocated to accommodate for a curb ramp)

D) Work orders (64)

| | |
|--------------------------------|-----------|
| LEAK - METER LEAK----- | 4 |
| DIS - DISCONNECT----- | 7 |
| CON - CONNECT----- | 8 |
| INFO - TEST METER ----- | 6 |
| MC - METER CHANGE ----- | 23 |
| OCC - OCCUPANT CHANGE----- | 0 |
| WATER BREAKS ----- | 1 |
| MISC-MISC REPORT ----- | 4 |
| HYDRT-HYDRANT LEAK----- | 0 |
| TEMP-TEMP SHUT OF REPAIR----- | 1 |
| SWR-SEWER PLUG UP----- | 1 |
| FIREFLY-FIREFLY REPLACE----- | 0 |
| ODOR - ODOR(TASTE/SMELL) ----- | 0 |
| TEST WATER PRESSURE----- | 1 |
| TOTAL ALL CODES | 64 |

Sincerely,

A handwritten signature in blue ink, appearing to read "Francisco Rodriguez".

Francisco Rodriguez
Chief Operator
Heber Public Utility District



Heber Public Utility District

1078 Dogwood Rd. Suite 103 • PO Box H

Heber CA 92249

Tel:(760)482-2440 • Fax (760)353-9951

www.heber.ca.gov

Nov 08, 2018

Attention: Mrs. Fischer

Subject: October 2018 Monthly Report

On the billing cycles ending on the 22th of October 27,768,000 gallons of water were used by our consumers, an average of 926,000 gallons was used per day.

On October 09, 2018 collected fourth quarter TTHM's samples and were sent to Clinical Lab of San Bernardino for analysis. The results came in on October 19, 2018 and were below the maximum contaminant level (MCL) for the both sites. The running annual average (RAA) MCL for TTHM's is 80 parts per billion (ppb) and for the 3rd quarter of 2018 we attained a RAA of 59.4 ppb for the Mc Cabe Cove site and 43.9 ppb for the Little Field site. Heber Public Utility District is in compliance with State and Federal water regulations.

On October 30, 2018 started draining water storage tank #1 (.75mg tank). The tank was inspected back in July 19, 2018 by Inland Potable Services and was found to have minor corrosion. The minor repairs will be completed this month of November by Pacific Hydrotech sub contractor, as both tanks are still under warranty.

If you have any questions, please contact me at (760) 427-4685


Sincerely,

A handwritten signature in blue ink, appearing to read "Francisco Rodriguez".

Francisco Rodriguez

Chief Operator

Heber Public Utility District



Heber Public Utility District

1078 Dogwood Rd, Suite 103 • P. O. Box H
Heber, CA 92249

TEL. (760) 482-2440 • FAX (760) 353-9951

www.heber.ca.gov

November 8, 2018

Attention: Laura Fischer
General Manager

SUBJECT: Heber W.W.T.P. Operation from September 22, 2018 to October 22, 2018

- A. Major violations: (NONE)
- B. Minor violations (NONE)
- C. Major sewer spills (NONE)
- D. Main sewer Plugs: (NONE)
- E. UV System: Operating fine. Self- Cleaning. No Maintenance.
- F. Vactor Truck:
October 4, 2018: Vactor truck was used to televise a sewer line on 1007 Heber Ave. to locate a service and verifying the number of sewer connections.
- G. TOTAL OF MILES CLEANED: 0 Miles.
- H. From September 22, 2018 through October 22, 2018:
Heber Wastewater Plant received and treated 14.31 MG.
- I. HPUUD did not exceed the daily maximum flow (1.2 MGD) as of October 22, 2018.

Sincerely,

A handwritten signature in blue ink, appearing to be "E. Gonzalez", written over a circular stamp or mark.

Edoardo S. Gonzalez
Wastewater Plant Operator

TTHM Data Chart July 2017 to Oct. 2018

